

SN: 071-0026

Bridge Condition Report

DISTRICT: 2

ROUTE: IL 2

SECTION: 38V (Original), 38VB-1 (Recon.)

COUNTY: Ogle

STRUCTURE NUMBER: 071-0026 (EXISTING)



LOCATION: IL 2 over the BN RR (1.2 miles South of IL 64)

PREPARED BY: Kenneth S. Couperus

DATE PREPARED: February 2008

PROPOSED LETTING DATE: Unknown

I. Geographical & Administrative Data:

Structure Number: 071-0026
County: Ogle
Route Carried: IL Route 2
Feature Crossed: Burlington Northern Railroad
Section: 38V (Original), 38VB-1 (Reconstruction)
Station: 7+68.1

Roadway Classification: Other Principal Arterial
Design/Posted Speed: 55 MPH/ 55 MPH
ADT (current/future): 2007 (4700) / 2021 (6700)
ADTT (current/future): 2007 (423) / 2021(603)
DHV: 470
Inventory Rating HS: 22.5
Operating Rating HS: 46.0
Sufficiency Rating: 53.0

Construction / Reconstruction / Repair History:

Construction: The original structure was built in **1928** as a four span Reinforced Concrete Tee Beam superstructure built on 2 spill through abutments and 3 multi column piers founded on spread footings with a 4 inch concrete wearing surface under SBI 2, Section 38V.

Reconstruction: During **1979**, new stub abutments were placed and the existing piers were widened both founded on metal shell concrete piles along with a new PPC Deck Beam superstructure and a bituminous concrete wearing surface under section 38VB-1, CN: 33302.

Note: Beams for span 1 and 4 were salvaged from SBI 86, section 105BR, Whiteside County, CN: 28136. These beams were cast in 1970, used briefly for a temporary structure and then stored at the Rock Falls Yard until 1979.

Rehabilitation: In **1996** the bituminous wearing surface was replaced with a 5" concrete overlay and all new expansion joints under section 38VB-1-M, CN: 64081.

II. Physical Description of Structure:

Structure 071-0026 is a simple four span PPC Deck Beam superstructure with 15 beam lines on two open reinforced concrete stub abutments founded on concrete and steel HP piles and three reinforced concrete multi column piers founded on spread footings (original portion) and concrete piles (widened portion) with zero skew angle. There are PJS expansion joints at the abutments and Piers 1 and 2.

There are no bearings (has fabric bearing pads) on this structure. There is a 5 inch thick concrete overlay on the superstructure.

The back-to-back abutment length is 231ft 6-1/2 inches and the span lengths are 62ft 3-1/2" (span 1), 54ft -4" (spans 2 & 3), and 61ft- 3" (span 4). All beams are 27" deep and 36" wide. The out-to-out deck width is 45ft.

The structure provides for one 12' traffic lane in each direction with 10ft concrete shoulders on each side. There are no sidewalks. The railing consists of a double steel tube type T mounted to W8 X 28 posts.

The existing structure is located on tangent horizontally and on the high point of a vertical curve near the North end of the structure. The approach roadway template at the South approach is a 24ft bituminous pavement with 10 ft concrete shoulders and at the North approach is a 24ft concrete pavement with 10ft concrete shoulders.

The slope walls consist of 4 inch thick concrete. **There are Power lines running under span 4 near the South face of Pier 3 which parallel the RR tracks.**

III. Field Inspection & Physical Evaluation:

Wearing Surface: The concrete overlay is **12** years old and in **satisfactory** condition. There are numerous hairline to narrow reflective keyway cracks showing over the majority of the structure.

The bridge rail, transitions and ends are substandard.

Superstructure: The superstructure is **29** years old and in **poor** condition. Note: The salvaged beams are 38 years old. There are 19 beams with areas of delaminations or spalls. 15 of the 19 are located at the beam ends. See the damage report and the survey in attachment E for locations and photos of damaged areas. A few of the worst beams are Beam 1 in Span 2 with 7 of 8 strands remaining in the bottom layer, Beam 2 in Span 3 with 5 of 8 strands remaining in the bottom layer and Beam 14 in Span 3 with 6 of 8 strands remaining in the bottom layer. The keyways are not leaking heavily yet and no independent movement has been identified.

Substructure: The original portions of the piers are **80** years old and the newer portions of the substructure are **29** years old and in **fair** condition. There are numerous locations of large spalls with exposed reinforcement and delaminations on all 3 piers. The North face of pier 1 is especially bad. There are several medium to wide cracks in the pier walls. The pier caps are heavily stained from leaking joints and wet most of the time. The abutment caps are stained from heavy leaking and are wet most of the time. There are several narrow vertical cracks visible on the caps.

The small wing walls exhibit narrow map cracking in small areas and are wet near the abutments.

Inspection History (NBIS Ratings):

Year	Deck (58)	Super (59)	Sub (60)
2007	4	4	5
2006 November	4	4	5
2006 May	6	6	5
2004	7	7	5
2003	7	7	5
2001	7	7	5
1999	7	7	5

Geometric/Hydraulic Data:

The deck geometry is rated a 6-equal to present minimum criteria and the under clearance-vertical and lateral appraisal are rated 4-minimum adequacy to be left in place and the structural evaluation is rated 4-minimum adequacy to be left in place. There is no waterway or drainage flowing under this structure

IV. Potential Scope of Work Determination & Analysis:

Due to the rapid deterioration, recent problems and concerns associated with PPC Deck beam superstructures, the age and condition of the substructure, and the unwritten policy that structures that have previously had major rehabilitations will not have them again (economically restrictive) it is recommended that the scope of work for this structure is complete structure replacement. Due to the above discussion elevation view surveys of the substructure showing deteriorated areas and a plan view deck survey showing delaminated areas are not provided in this Bridge Condition Report.

V. Discussion and Recommended Scope of Work:

The recommended scope of work for this structure is complete replacement at an estimated cost of \$1,252,800.00.

Traffic Control: Because this is a deck beam superstructure, the traffic control during construction should be evaluated during Phase I in programming using TMA-Traffic Management Analysis. (To be determined by Program Development). Note: for staging purposes both directions are in similar condition at the time of this BCR preparation. **During the 1979 reconstruction the traffic was detoured. Coordination with the RR will also be required-i.e. flaggers.**

ATTACHMENTS:

Illinois Department of Transportation
Structures Information Management System
Master Structure Report (S-107)

Date: 12/24/2007

Page 1

Structure Number: 071-0026 District: 2

Inventory Data

Facility Carried:	ILL 2	Bridge Name:		Sufficiency Rating:	53.0	Structure Length:	232.0
Feature Crossed:	BN RAILROAD	Location:	S EDGE OREGON	HBRRP Eligible:	Yes	AASHTO Bridge Length:	99.9
Bridge Remarks:		StatusDate:	04/1988	Replaced By:	000-0000	Length of Long Span:	61.0
Bridge Status:	1 OPEN - NO RESTRICT			Replaces:	000-0000	Bridge Roadway Width:	43.0
Status Remarks:				Last Update Date:	12/11/2007	Appr Roadway Width:	44.0
Maint County:	071 OGLE	Maint Township:	26 OREGON-NASHUA	Parallel Structure:	None	Deck Width:	45.0
Maint Responsibility:	01 I.D.O.T.			Multi-Level Structure Nbr:		Sidewalk Width Right:	0.0
Service On/Under:	1 HIGHWAY		/ 2 RAILROAD	Skew Direction:	None	Sidewalk Width Left:	0.0
Reporting Agency:	1 I.D.O.T. - BUREAU OF MAINTENANCE			Skew Angle:	00 D 00 M 00 S	Navigation Control:	N/A
Main Span Matl/Type:	5 PRESTRESS CONCRETE		/ 05 BOX BEAM OR GIRDER-MULTIPLE	Structure Flared:	No	Navigation Horiz Clear:	0
Nbr Of Main Spans:	4	Nbr Of Approach Spans:	0	Historical Significance:	No	Navigation Vert Clear:	0
Approaches							
Near #1 Matl/Type:				Border Bridge State:		Culvert Fill Depth:	0.0
Near #2 Matl/Type:				Bdr State SN:		Number Culvert Cells:	0
Far #1 Matl/Type:				Bdr State % Responsibility:	0	Culvert Opening Area:	0.0
Far #2 Matl/Type:				Structural Steel Wt:	0	Culvert Cell Height:	0.00
Median Width/Type:	0 Ft / 0 None			Substructure Material:		Culvert Cell Width:	0.00
Guardrail Type L/R:	0 None / 0 None			Rated By:	2 IDOT	Rate Method:	1 LOAD FACTOR
Toll Facility Indicator:	0 No Toll			Load Rating Date:	07/13/2007	***Railroad Crossing Info***	
Latitude:	42 D 00 M 6.43 S	Longitude:	89 D 20 M 14.13 S	Inventory Rating:	22.5 (241)	Crossing 1 Nbr:	009826H
Deck Structure Type:	E PCAST PRES CN DK BM	Deck Structure Thickness:	27.0	Operating Rating:	46.0 (283)	Crossing 1 Nbr:	
Sidewalks Under Structure:	0 None			Design Load:	02 HS20	RR Lateral Underclear:	08.0

Key Route On Data

Key Route Nbr:	FEDERAL-AID PRIMARY	Station:	018.320
Appurtenances	Main Route	Segment:	
Inventory County:	071 OGLE	Linked:	Y
Township/Road Dist	26 OREGON-NASHUA	Natl. Hwy System:	
Municipality	4425 OREGON	Inventory Direction:	
Urban Area:	None	Curr AADT Yr/Count:	2007 / 4700
Functional Class:	30 OTHER PRINCIPAL ARTERIAL	Est Truck Percentage:	9
** CLEARANCES ** South/East North/West			
Max Rdwy Width:	043.0	Number Of Lanes:	2 Two-Way
Horizontal:	044.5	One Or Two Way:	30
Min Vertical:	99 Ft 11 In	Bypass Length:	2021 / 6700
10 Ft Vertical:	99 Ft 11 In	Future AADT Yr/Cnt:	CLASS II
Lateral:		Designated Truck Rte:	No
		Special Systems:	

*** Marked Route On Data ***

Route #1:	1 Mainline	Designation	Kind	Number
Route #2:				0002
Route #3:				

Key Route Under Data

Station:	
Segment:	
Linked:	
Natl. Hwy System:	
Inventory Direction:	
Curr AADT Yr/Count:	/
Est Truck Percentage:	
Number Of Lanes:	
One Or Two Way:	
Bypass Length:	
Future AADT Yr/Cnt:	/
Designated Truck Rte:	
Special Systems:	

*** Marked Route Under Data ***

Designation	Kind	Number

Illinois Department of Transportation
Structures Information Management System
Master Structure Report (S-107)

Date: 12/24/2007

Page 2

Structure Number: 071-0026 District: 2

Data Related to Inspection Information

***Inspection Intervals ***

Routine NBIS: 12 MOS Underwater: 0 MOS One Truck At A Time: 0 MOS
Fracture Critical: 0 MOS Special: 0 MOS Single Unit Vehicles: 0 Tons

*** Maximum Allowable Posting Limits ***

Combination Type 3S-1: 0 Tons
Combination Type 3S-2: 0 Tons

Bridge Posting Level:

5 No Posting Required

Inspection/Appraisal Information

Inspection Date:	10/22/2007	Inspection Temperature:	50 Deg. F	Inspection by (Name):	MARDAUSSRW	** Actual Posted Limits **
Deck:	4 POOR CONDITION - ADVANCED DETERIORATION	Inspection Category:	50	Inspection Method:		Single Unit Vehicles: 0 Tons
Superstructure:	4 POOR CONDITION - ADVANCED DETERIORATION	Inspection Category:	50	Inspection Method:		Combination Type 3S-1: 0 Tons
Substructure:	5 FAIR CONDITION - MINOR SECTION LOSS, CRACKS	Inspection Category:	50	Inspection Method:		Combination Type 3S-2: 0 Tons
Culvert:	N NOT APPLICABLE	Inspection Category:	50	Inspection Method:		One Truck At A Time: 0 Tons
Channel and Protection:	N NOT APPLICABLE	Inspection Category:	50	Inspection Method:		
Structural Evaluation:	4 MINIMUM ADEQUACY TO BE LEFT IN PLACE	Inspection Category:	50	Inspection Method:		
Deck Geometry:	6 EQUAL TO PRESENT MINIMUM CRITERIA	Inspection Category:	50	Inspection Method:		
Underclearance-Vert/Lat:	4 MINIMUM ADEQUACY TO BE LEFT IN PLACE	Inspection Category:	50	Inspection Method:		
Waterway Adequacy:	N NOT APPLICABLE	Inspection Category:	50	Inspection Method:		
Approach Roadway Align:	8 EQUAL TO PRESENT DESIRABLE CRITERIA	Inspection Category:	50	Inspection Method:		
Bridge Railing Appraisal:	2 Doesn't Meet Standards	Inspection Category:	50	Inspection Method:		
Approach Guardrail:	2 Acceptable Not Acceptable	Inspection Category:	50	Inspection Method:		
Pier Navig Protection:	N N/A	Inspection Category:	50	Inspection Method:		

Underwater Inspection/Appraisal Information

Inspection Date:		Inspection Category:		Inspection Method:	
Temperature:		Inspection Category:		Inspection Method:	
Inspected By:		Inspected By:		Appraisal Rating:	
Inspection Remarks:					

Scour Critical Information

Rating:		Evaluation Method:		Analysis By:	
Analysis Date:		Evaluation Method:		Analysis By:	

Miscellaneous

Fracture Critical Members:	No
Microfilm Data Recorded:	Yes

Construction Information

Year:	1929 Original	1979 Reconstructed
Route:	FA 742 Sta: 7+68.10	FA 742 Sta: 7+68.10
Section Nbr:	38-V	38VB-1
Contract Nbr:		
Fed Aid Pr #:	0000000000000000	0000000000000000
Built By:	1 I.D.O.T.	1 I.D.O.T.

Waterway Information

Flood Design Frequency:	0 YRS	Drainage Area:	0 Acre
Flood Design Q (CFS):	0	Flood Base Q (CFS):	0
Flood Design Nat H W E:	0	Flood Base Nat H W E:	0
Flood Des Open Prop:	0 SF		

Proposed Improvement

Cost Estimate Year:		Length:		*** Costs in Dollars ***
Type of Work:		Bridge Cost:		
Done By:		Roadway Cost:		
Remarks:		Total Project Cost:		



Structure Number: 071-0026

Maint. Co:	OGLE	Twsp:	OREGON-NASHUA	Status:	OPEN - NO RESTRICT
Facility Carried:	ILL 2	Feature Crossed:	BN RAILROAD	Team/Sub	
Location:	S EDGE OREGON	Municipality:	OREGON	Section	
Total # Spans:	4	Material:	PRESTRESS CONCRETE	Type:	BOX BEAM OR GIRDER-MULTIPLE
Inspection Intervals (Mo.):	Routine NBIS	12	/ Fracture Critical	0	/ Underwater - 0

90 – Inspection Date:		/ /		90C – Temp. (°F):				93C – Special Inspection Date:		/ /	
90A – Inspection Team Leader:								Qualification:			

	Prev	New		Prev	New		Prev	New
58 – Deck Condition:	4		62 – Culvert Condition:	N		72 – Approach Rdwy Align:	8	
59 – Superstructure Cond:	4		61 – Channel Condition:	N		111 – Pier Navig Protection:	N	
60 – Substructure Cond:	5		71 – Waterway Adequacy:	N		Appraisal Comments:		

		Prev	New			Prev	New			Prev	New
36A – Bridge Railing Adequacy:		2				Prev	New	36C – Guardrail:		3	
Approach Guardrail Adequacy:				36B – Transitions:		2		36D – Ends:		2	

Prev			New			Prev			New								
108A – Wearing Surface Type:			B			108B – Type of Membrane:			A			108C – Deck Protection:			J		
108D – Total Deck Thickness (In.):			33.3			Deck Comments:											

	Prev	New	
59A – Paint Date (Mo/Yr):		/	Paint Comments:
59B – Paint Systems:			Color: Fascia – ____; Inter. – ____; Railing – ____.
59C – Utilities Attached:	NNN		Utilities Comments:

		Prev	New			Prev	New
Weight Limit Posting:	70A2 – Single Unit Vehicles:		T.				
	Combination Vehicles: 70B2 – 3 or 4 Axles:		T.	70C2 – 5 or More Axles:			T.
	70D2 – One Truck at a Time:			Posting Comments:			

90B – Inspection Remarks: (Note: 237 characters maximum)

New Inspection	
Previous Inspection	

	Signature	Date	Supervisor Init. & Date
Inspection Team Leader:		/ /	



Element Level Field Inspection Report

SN: 0710026 District: 2 Spans: 4 Appr. Spans: 0 Skew: 00 ADT: 4700 Truck Pct: 9 ADT Un: 0

Facility Carried: ILL 2

Name:

Feature Crossed: BN RAILROAD

Location: S EDGE OREGON

Inspection Date: 10/23/2007

Inspection Notes: Numerous reflective keyway cracks to WS.

Inspector 1: COUPERUSKS

Inspector 2:

Temp: 50

Resources

Time to Insp:	0:30	Trffc Ctrl:	1	Boat:		Waders:		Snooper:	
		Ladder:		Manlift:		Other:			

Inspector's Appraisals

Elem	Element Desc	Env	Quantity	Un	CS1	CS2	CS3	CS4	CS5
22	Concrete Deck Protected w/ Rigid Overlay	3	10269	SF	10269	0	0	0	0
Remarks: Numerous reflective keyway cracks to WS.									
104	P/S Conc Closed Web/Box Girder	3	3420	LF	3190	0	50	180	0
Remarks:									
108	Keyway	3	3248	LF	3248	0	0	0	0
Remarks:									
205	Reinforced Conc Column or Pile Extension	1	2948	SF	2518	150	280	0	0
Remarks:									
210	Reinforced Conc Pier Wall	1	5088	SF	4908	60	120	0	0
Remarks:									
215	Reinforced Conc Abutment	1	345	SF	315	30	0	0	0
Remarks: Wet from leaking joints.									



Element Level Field Inspection Report

SN: 0710026 District: 2 Spans: 4 Appr. Spans: 0 Skew: 00 ADT: 4700 Truck Pct: 9 ADT Un: 0

234	Reinforced Conc Pier or Abutment Cap	1	231	LF	156	75	0	0	0
Remarks:		Wet from leaking joints.							
302	Preformed Joint Seal	3	225	LF	90	135	0	0	0
Remarks:		Numerous PJS leaking							
323	Approach Pavement	3	2	EA	2	0	0	0	0
Remarks:									
330	Metal Bridge Railing	3	459	LF	459	0	0	0	0
Remarks:									

Inspected By: _____